

ATTACHMENT "A"

ADD ALTERNATE #1

Interior Piping

Condition Rating Poor

Assessment Corrosion noted on interior DIP lines.

Recommendation Prepare surface of corroded DIP lines and coat with a polyamidoamine epoxy.

Photos

