Instr# 114696312 , Page 1 of 2, Recorded 11/01/2017 at 08:29 AM

Broward County Commission Deed Doc Stamps: \$7700.00

> Prepared by and return to: Patricia A. Rathburn

Patricia A. Rathburn P.A. 500 SE 17th Street Suite 312 Fort Lauderdale, FL 33316 954-764-6166 File Number: CC eynolds

Will Call No.:

Parcel Identification No. 474232010200

[Space Above This Line For Recording Data]_

Warranty Deed

(STATUTORY FORM - SECTION 689.02, F.S.)

This Indenture made this 31st day of October, 2017 between James Reynolds, a married man whose post office address is 501 Seagate Drive, Delray Beach, FL 33483 of the County of Palm Beach, State of Florida, grantor*, and City of Coconut Creek whose post office address is 4800 W. Copans Road, Coconut Creek, FL 33063 of the County of Broward, State of Florida, grantee*,

Witnesseth that said grantor, for and in consideration of the sum of TEN AND NO/100 DOLLARS (\$10.00) and other good and valuable considerations to said grantor in hand paid by said grantee, the receipt whereof is hereby acknowledged, has granted, bargained, and sold to the said grantee, and grantee's heirs and assigns forever, the following described land, situate, lying and being in Broward County, Florida, to-wit:

Tract Forty- Four (44) in Block Eighty-Three (83) of PALM BEACH FARMS, according to the Plat thereof, as recorded in Plat Book 2, Page 53, of the Public Records of Palm Beach County, Florida, said lands situate lying and being in Broward County, Florida.

and said grantor does hereby fully warrant the title to said land, and will defend the same against lawful claims of all persons whomsoever.

Grantor covenants and warrants that the above described property is not his homestead nor is it the homestead of any member of his family and that in fact Grantor resides at 501 Seagate Drive, Delray Beach, Florida.

* "Grantor" and "Grantee" are used for singular or plural, as context requires.

In Witness Whereof, grantor has hereunto set grantor's hand and seal the day and year first above written.

delivered in our presence: Signed, sealed and

Witness Namé atricia

(Seal)

kens Republis

Instr# 114696312 , Page 2 of 2, End of Document

State of Florida	
County of Broward	Possible and
The foregoing instrument was acknowledged before me	this 31st day of October 2011 by James Reynolds. Who
[_] is personally known or [X] has produced a driver's lic	ense as identification.
[Notary Seal]	Notary Public
	Printed Name:
	My Commission Expires:

PATRICIA A RATHBURN
MY COMMISSION # GG 066030
EXPIRES: February 12, 2021
Bonded Thru Budgel Notary Services

CFN # 107445318, OR BK 44714 Page 599, Page 1 of 3, Recorded 10/15/2007 at 11:08 AM, Broward County Commission, Deputy Clerk 1923

This instrument prepared by:
Noel M. Pfeffer, Deputy County Attorney
Broward County Attorney's Office
115 South Andrews Ave, Rm. 423
Fort Lauderdale, FL 33301
954-357-7600

QUIT CLAIM DEED

(Pursuant to F. S. 125.411)

THIS DEED, made this day of _______, 2007, by BROWARD COUNTY, a political subdivision of the State of Florida (the "GRANTOR"), whose address is Governmental Center, Room 423, 115 South Andrews Avenue, Fort Lauderdale, Florida 33301, and CITY OF COCONUT CREEK, a Florida municipal corporation (the "GRANTEE"), whose address is: 4800 West Copans Road, Coconut Creek, FL 33063.

WITNESSETH:

That GRANTOR for and in consideration of the sum of TEN DOLLARS (\$10.00) to it in hand paid by GRANTEE, the receipt whereof is hereby acknowledged, has granted, bargained and sold to GRANTEE, its heirs, successors and assigns, forever, the following described lands, lying and being in Broward County, Florida, to wit:

(See attached Exhibit A)

SUBJECT TO:

- 1. All matters of record including existing public purpose utility and government easements and rights of way.
- 2. An Interlocal Agreement between Broward County and City of Coconut Creek for the Acquisition, Improvement, Enhancement, Operation and Management of Green Space # 24, recorded simultaneously herewith;
- 3. Deed of Conservation Easement given the 10th day of September 2002 by Alfredo and Anna Aletto to Broward County, a political subdivision of the State of Florida, its successors and assigns, as recorded in O.R. Book 35123 Pages 1097-1110, Public Records of Broward County, Florida; and
- 4. Resolution of the Board of County Commissioners of Broward County, Florida approving the conveyance pursuant to Section 125.38 F.S. recorded simultaneously herewith.



IN WITNESS WHEREOF, GRANTOR has caused these presents to be executed in its name by its Board of County Commissioners acting by the Mayor or Vice-Mayor of said Board, the day and year aforesaid.

(Official Seal) ATTEST:

County Administrator and
Ex-Officio Clerk of the
Board of County Commissioners
of Broward County, Florida



BROWARD COUNTY, FLORIDA
By Its Board of County Commissioners

By Joen Well Mayor

9th day of October, 2007

Approved as to form by
Office of County Attorney
Broward County, Florida
JEFFREY J. NEWTON, County Attorney
Governmental Center, Suite 423
115 South Andrews Avenue
Fort Lauderdale, Florida 33301
Telephone: (954) 357-7600

Telecopier: (954) 357-6968

By Deputy County Attorney

4 day of Octoba, 2007

Exhibit A

Legal Description of Property

Tract 43, Block 83 of Palm Beach Farms Company Plat No. 3, as recorded in Plat Book 2, Page 45, of the public records of Palm Beach County

Instr# 114827496 , Page 1 of 2, Recorded 01/12/2018 at 08:22 AM

Broward County Commission Deed Doc Stamps: \$11865.70

> Prepared by and return to: Patricia A. Rathburn

Patricia A. Rathburn P.A. 500 SE 17th Street Suite 312 Fort Lauderdale, FL 33316 954-764-6166 File Number: CC lehigh

Will Call No .:

Parcel Identification No. 474232010180

[Space Above This Line For Recording Data]_

Warranty Deed (STATUTORY FORM - SECTION 689.02, F.S.)

This Indenture made this 11th day of January, 2018 between MG Lehigh Acres Holding LLC, a Florida limited liability company whose post office address is 2295 NW Corpoate Blvd., STE 235, Boca Raton, FL 33431-7330 of the County of Palm Beach, State of Florida, grantor*, and City of Coconut Creek whose post office address is 4800 W. Copans Road, Coconut Creek, FL 33063 of the County of Broward, State of Florida, grantee*,

Witnesseth that said grantor, for and in consideration of the sum of TEN AND NO/100 DOLLARS (\$10.00) and other good and valuable considerations to said grantor in hand paid by said grantee, the receipt whereof is hereby acknowledged, has granted, bargained, and sold to the said grantee, and grantee's heirs and assigns forever, the following described land, situate, lying and being in Broward County, Florida, to-wit:

Tract 42, Block 83 of PALM BEACH FARMS COMPANY PLAT NO. 3, according to the Plat thereof recorded in Plat Book 2 at pages 45-54 of the Public Records of Palm Beach County, Florida; said land situate, lying and being in Broward County, Florida.

and said grantor does hereby fully warrant the title to said land, and will defend the same against lawful claims of all persons whomsoever.

* "Grantor" and "Grantee" are used for singular or plural, as context requires.

In Witness Whereof, grantor has hereunto set grantor's hand and seal the day and year first above written.

Signed, sealed and delivered in our presence:

Witness Name:

MG Lehigh Acres Holding LLC

Witness Name: LINDA LIEBERMAN

Instr# 114827496 , Page 2 of 2, End of Document

State of Florida County of Broward	
The foregoing instrument was acknowledged before m Manager of MG Lehigh Acres Holding LLC, on behalf of known to me or [X] has produced a driver's license as ide	of the limited liability company. He/she i is personally
[Notary Seal]	Notary Public
PATRICIA A RATHBURN MY COMMISSION # GG 068030	Printed Name:
EXPIRES: February 12, 2021 Sor FLOR Bonded Thru Budget Notary Services	My Commission Expires:



DEPARTMENT OF SUSTAINABLE DEVELOPMENT

4800 WEST COPANS ROAD COCONUT CREEK, FLORIDA 33063


REZONING JUSTIFICATION STATEMENT

Please fill out the following in COMPLETE DETAIL, a restatement does not satisfy code requirements


1.	Is not contrary to the Comprehensive Plan.						
	·						
	The proposed rezoning of two 5 AC parcels to P - Parks and Recreation aligns with the intent of the Comprehensive Plan and increases park acreage in the City.						
2.	Will not create an isolated zoning district, which would be unrelated and incompatible with adjacent districts.						
	The center parcel is already zoned as P - Parks and Recreation so the newly zoned parcels will be adjacent use.						
3.	Will not substantially impact public facilities such as schools, utilities and streets.						
	The proposed site improvements include on-site utility improvements to provide the necessary infrastructure for intended use of the site, the site will provide more recreational space for nearby schools and the park is expected to be a passive use. This rezoning will have no negative effects on public schools, utilities, or streets.						
4.	Will be justified by external land use conditions.						
	The zoning of P - Parks and Recreation aligns with the future land use designation for these parcels.						
5 .	Will not create or excessively increase automobile and vehicular traffic congestion.						
	This project will not excessively increase automobile and vehicular traffic congestion, 29 paved parking spaces and 66 Overflow spaces are being proposed on the site plan, 7 of the paved parking spaces are existing. The proposed park will be a passive use park with no regularly scheduled sports or activities.						
6.	Will not create a storm drainage problem for other properties.						
	All stormwater runoff will be contained on site through proposed dry detention, it will not influence other properties.						
7.	Will not adversely affect surrounding living conditions.						
	Fencing and vegetative buffers are being installed adjacent to residential uses; the park will be closed at nighttime. The proposed park will be a passive use park.						
8.	Will not adversely affect environmental quality.						
	Any trees to be removed are invasive/exotic or are in direct conflict with the proposed improvements, one acre of native vegetation and required mitigation trees will be planted on site.						
9.	Will not adversely affect other property values.						
	The proposed site is a public park that will add value to nearby properties and the community.						
10.	Will not be a deterrent to improvement or development of other property.						
	The proposed improvements on the site are contained within the property boundary and do not affect development of other properties.						
11.	Will not constitute a special privilege to an individual owner.						
	This property will be a passive park open to the public during the day and closed at nighttime.						

PHONE (954) 973-6756 FAX (954) 956-1424 www.coconutcreek.net

2




	OWN	CHICAGO TITLE INSURAN ERSHIP & ENCUMBRANCE SEARC DATE: DECEMBER 11, 20	CH, CERTIFICATE NO. 48172		
ITEM NO.	INSTRUMENT	DESCRIPTION	RECORDING DATA	AFFECTS	PLOTTED
1	PLAT	RESERVATIONS AS CONTAINED IN THE PLAT OF PALM BEACH FARMS COMPANY PLAT NO.3	P.B. 2, PG. 45-54, P.B.C.R.	YES	YES
2	DEED #2972	TIFF RESERVATIONS	D.B. 549, PG. 211, B.C.R.	YES	YES (TRACT 43)
3	DEED #5513	DRAINAGE RESERVATIONS	D.B. 553, PG. 284, B.C.R.	YES	YES (TRACT 43)
4	EASEMENT	FLORIDA POWER & LIGHT COMPANY EASEMENT	O.R.B. 8343, PG. 170, B.C.R.	YES	YES
5	WARRANTY DEED	RESTRICTIVE COVENANTS	O.R.B. 14704, PG. 526, B.C.R.	YES	YES (TRACT 42)
6	EASEMENTS	OFFICIAL RECORD	O.R.B. 15519, PG. 987, B.C.R.	YES	YES
7	WARRANTY DEED	DESTRICTIVE COMENIANTS	O.R.B. 33054, PG. 1571, B.C.R.	YES	YES (TRACT 42)
7	WARRANTY DEED	RESTRICTIVE COVENANTS	O.R.B. 33948, PG. 1254, B.C.R.	YES	YES (TRACT 42)
8	ORDINANCE NO. 2002-015	OFFICIAL RECORD	O.R.B. 34541, PG. 289, B.C.R.	YES	YES (TRACT 43)
9	DEED	CONSERVATION EASEMENT	O.R.B. 35123, PG. 1097, B.C.R.	YES	YES (TRACT 43)
10	FLORIDA RESOLUTION 2007-696	OFFICIAL RECORD	O.R.B. 44714, PG. 566, B.C.R.	YES	YES (TRACT 43)
11	INTERLOCAL AGREEMENT	OFFICIAL RECORD	O.R.B. 44714, PG. 572, B.C.R.	YES	YES (TRACT 43)
12	FLORIDA ORDINANCE NO. 2015-027	OFFICIAL RECORD	INSTRUMENT #113260344	YES	YES (TRACT 42)
13	FLORIDA ORDINANCE NO. 2018-014	OFFICIAL RECORD	INSTRUMENT #115233139	YES	YES (TRACT 44)
14	NOT SURVEY PERTINENT	TAXES FOR YEAR 2023			



DESCRIPTION:

TRACTS 42, 43 AND 44 OF PALM BEACH FARMS PLAT NO.3, ACCORDING TO THE PLAT THEREOF AS RECORDED IN PLAT BOOK 2, AT PAGES 45 THROUGH 54, OF THE PUBLIC RECORDS OF PALM BEACH COUNTY, FLORIDA;

SAID LANDS SITUATE, LYING AND BEING IN THE CITY OF COCONUT CREEK, BROWARD COUNTY, FLORIDA AND CONTAINING 653,424 SQUARE FEET (15.000 ACRES) MORE OR LESS.



--- SSFM --- UNDERGROUND FORCE MAIN

— E — UNDERGROUND ELECTRIC LINE

_____ W ____ UNDERGROUND WATER LINE

SYMBOL LEGEND:

— STREET SIGN

FLOOD INSURANCE NOTES:

MOST OF THE SUBJECT PROPERTY LIES IN FLOOD ZONE X, WITH THE EXCEPTION OF A SMALL PORTION OF THE NORTHEAST CORNER OF TRACT 42 (P.B. 2, PG. 45-54, P.B.C.R.) LIES IN FLOOD ZONE AH WITH A BASE FLOOD ELEVATION OF 16 FEET. COMMUNITY PANEL NO. 125093 0158 H (UNINCORPORATED BROWARD COUNTY) PER FIRM DATED AUGUST 18, 2014 MAP NO. 12011C 0158 H

SURVEYORS NOTES:

1. ELEVATIONS SHOWN HEREON ARE RELATIVE TO NORTH AMERICAN DATUM OF 1988 AND ARE BASED ON NATIONAL GEODETIC SURVEY BENCHMARK AD8517 WITH DESIGNATION: "PILING" AND LOCATED AT WEST EDGE OF CONCRETE SIDEWALK ON THE WEST SIDE OF LYONS ROAD JUST SOUTH OF THE HILLSBOROUGH CANAL BRIDGE. ELEVATION = 15.11

2. BEARINGS SHOWN HEREON ARE BASED ON A BEARING OF N89°35'56"E ALONG THE SOUTH RIGHT-OF-WAY OF NW 74th STREET.

3. THIS SURVEY WAS PREPARED WITH THE BENEFIT OF AN OWNERSHIP ENCUMBRANCE REPORT PREPARED BY CHICAGO TITLE INSURANCE AGENCY.

4. SEE SHEETS 2-5 FOR SURVEY AND SHEETS 6-7 FOR TREE DISPOSITION CHART.

5. UTILITIES ARE DEPICTED PER A SUBSURFACE UTILITY INVESTIGATION CONDUCTED ON FEBRUARY 3RD 2024. INDUSTRY STANDARD GEOPHYSICAL PROSPECTING TECHNIQUES WERE USED IN CONJUNCTION WITH GROUND PENETRATING RADAR TO DETECT UNDERGROUND UTILITY LINES IN AREAS SPECIFIED BY THE CLIENT. DUE TO SITE CONDITIONS AND INHERENT LIMITATIONS WITH CURRENT TECHNOLOGY, NO GUARANTEE IS EXPRESSED THAT ALL UTILITIES WERE SUCCESSFULLY DETECTED AND LOCATED. CLIENT / CONTRACTOR IS HEREBY ADVISED TO CONTACT SUNSHINE STATE ONE CALL OF FLORIDA AT 811 PRIOR TO ANY EXCAVATION. MILLER LEGG SHALL NOT BE HELD LIABLE FOR DAMAGE CAUSED TO UTILITIES DURING CONSTRUCTION.



954-436-7000 www.millerlegg.com

CONSULTANTS:

ARCHITECT: **Justin Architects** 2400 E. Commercial Boulevard, Suite 201 Fort Lauderdale, FL 33308 (954) 771-2724 www.justinarc.com

SGM Engineering 5805 Blue Lagoon Drive, Suite 285 Miami, Florida 33026 (954) 421-1944 www.sgmengineering.com

STRUCTURAL ENGINEER: Master Consulting Engineers 4101 Ravenswood Road, Suite 320 Fort Lauderdale, Florida 33312 (954) 210-7671 www.mcengineers.com

SUSTAINABILITY CONSULTANT: SOCOTEC Consulting, Inc. 1177 Clare Avenue, Suite 7 West Palm Beach, Florida 33401 (561) 801-7576 www.spinnakergroup.com

GEOTECHNICAL Pacifica Engineering Services 601 N. Congress Avenue, Suite 303 Delray Beach, Florida 33445 (561) 419-8460 www.pacificaes.com

CLIENT:




4900 W. Copans Road Coconut Creek, FL 33063

PROJECT NAME:

OAK TRAILS PARK **IMPROVEMENTS**

4230 NW. 74th Street Coconut Creek, FL 33073

I HEREBY CERTIFY THAT THE INFORMATION HEREON MEETS STANDARDS OF PRACTICE AS SET FORTH BY THE FLORIDA DEPARTMENT OF AGRICULTURE AND CONSUMER SERVICES OF PROFESSIONAL SURVEYORS AND MAPPERS IN CHAPTE 5J-17, FLORIDA ADMINISTRATIVE CODE, PURSUANT T



NOT VALID WITHOUT THE SIGNATURE AND THE ORIGINAL RAISED SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER.

APPROVED: MARTIN P. ROSSI, PSM

FLA. REGISTRATION NO. 5857 DATE 02/12/24

1	09/12/24	DRC S	SITE	PLAN	RESUE	BMITTA	L	
1	07/29/24	REV.	ТО	SHOW	ELEC.	SERV.	BOX	SYME
NO.	DATE			F	REVI	SIOI	N S	

SUBMITTAL:

DRC SUBMITTAL


DATE ISSUED: **PROJECT NUMBER: DRAWN BY: REVIEWED BY: DESIGNED BY:**


23-00155


SHEET TITLE:

SKETCH OF BOUNDARY & TOPOGRAPHIC SURVEY


SHEET NUMBER:







I HEREBY CERTIFY THAT THE INFORMATION HEREON MEETS STANDARDS OF PRACTICE AS SET FORTH BY THE FLORIDA DEPARTMENT OF





Justin Architects 2400 E. Commercial Boulevard, Suite 201 Fort Lauderdale, FL 33308

SGM Engineering 5805 Blue Lagoon Drive, Suite 285 Miami, Florida 33026 (954) 421-1944 www.sgmengineering.com

STRUCTURAL ENGINEER: Master Consulting Engineers 4101 Ravenswood Road, Suite 320 Fort Lauderdale, Florida 33312 (954) 210-7671 www.mcengineers.com

SUSTAINABILITY CONSULTANT: SOCOTEC Consulting, Inc. 1177 Clare Avenue, Suite 7 West Palm Beach, Florida 33401 (561) 801-7576

GEOTECHNICAL: Pacifica Engineering Services 601 N. Congress Avenue, Suite 303 Delray Beach, Florida 33445 (561) 419-8460 www.pacificaes.com




4900 W. Copans Road Coconut Creek, FL 33063

PROJECT NAME:

OAK TRAILS PARK **IMPROVEMENTS**

4230 NW. 74th Street Coconut Creek, FL 33073

I HEREBY CERTIFY THAT THE INFORMATION HEREON MEETS STANDARDS OF PRACTICE AS SET FORTH BY THE FLORIDA DEPARTMENT OF AGRICULTURE AND CONSUMER SERVICES OF ROFESSIONAL SURVEYORS AND MAPPERS IN CHAPTE 5J-17, FLORIDA ADMINISTRATIVE CODE, PURSUANT T SECTION 472.027, FLORIDA STATUTES.



HE ORIGINAL RAISED SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER.

PROVED: MARTIN P. ROSSI, PSM

1	09/12/24	DRC	SITE	PLAN	RESUE	BMITTA	L	
1	07/29/24	REV.	TO	SHOW	ELEC.	SERV.	BOX	SYMBOLS

REVISIONS


DRC SUBMITTAL

DATE ISSUED: PROJECT NUMBER: **REVIEWED BY:**

23-00155

09/16/2024

SKETCH OF BOUNDARY &



	TREE INVENTORY CHART										
ID#	Common Name	Botanical Name	DBH (inches)	Height (feet)	Spread (feet)	Condition	Notes				
1 2	Solitaire Palm Live Oak	Ptychosperma elegans Quercus virginiana	3 8	20 24	6 24	Good Good					
3	Cabbage Palm	Sabal palmetto	12	3	12	Good					
5	Cabbage Palm Slash Pine	Sabal palmetto Pinus elliottii	10 13	8 42	12 24	Good Good					
6	Cabbage Palm	Sabal palmetto	10	8	10	Good					
7 8	Black Olive Slash Pine	Bucida buceras Pinus elliottii	17 20	32 42	34 26	Fair Good	Bent Leader Co-Dominant Leaders Included Bark				
9	Christmas Palm	Adonidia merrillii	6	6	8	Good					
10	Cabbage Palm Slash Pine	Sabal palmetto	12	24	14	Good	Co Dominant Londors Llimb Domago Minor				
11 12	Laurel Oak	Pinus elliottii Quercus laurifolia	31 12	42 38	50 36	Fair Good	Co-Dominant Leaders Limb Damage - Minor				
13	Black Olive	Bucida buceras	23	42	46	Good					
14 15	Christmas Palm Montgomery Palm	Adonidia merrillii Veitchia arecina	5 4	8 14	6 6	Good Good					
16	Slash Pine	Pinus elliottii	8	32	20	Fair	Limb Damage - Minor Lopsided Poor Structure				
17 18	Black Olive Cabbage Palm	Bucida buceras Sabal palmetto	23 10	38 14	60 14	Good Good	Limb Damage - Minor Sprouting				
19	Weeping Fig	Ficus benjamina	8	22	14	Good					
20 21	Christmas Palm Christmas Palm	Adonidia merrillii Adonidia merrillii	6 6	<u>8</u> 6	6	Good Good					
22	Cabbage Palm	Sabal palmetto	10	16	14	Good					
23	Christmas Palm Live Oak	Adonidia merrillii Quercus virginiana	5 18	8 46	6 44	Good Good	Leaning - Minor				
25	Cabbage Palm	Sabal palmetto	12	14	12	Fair	Bent Trunk				
26 27	Christmas Palm Cabbage Palm	Adonidia merrillii Sabal palmetto	6 12	14 16	6 12	Good Good					
28	Weeping Fig	Ficus benjamina	16	34	40	Fair	Apical Dieback Co-Dominant Leaders Limb Damage - Minor				
29 30	Laurel Oak Cabbage Palm	Quercus laurifolia Sabal palmetto	24 8	44 14	50 12	Fair Good	Co-Dominant Leaders Limb Damage - Minor				
31	Black Olive	Bucida buceras	16	38	36	Good	Bent Leader Limb Damage - Minor				
32 33	Cabbage Palm	Sabal palmetto	10	16 46	12	Fair	Bent Trunk				
33	Slash Pine Cabbage Palm	Pinus elliottii Sabal palmetto	20 11	46 16	40 14	Good Good					
35	Slash Pine	Pinus elliottii	20	42	34	Good	Limb Damaga Minar				
36 37	Slash Pine Solitaire Palm	Pinus elliottii Ptychosperma elegans	20	48	36	Good Dead	Limb Damage - Minor				
38	Weeping Fig	Ficus benjamina	10	28	26	Fair	Bent Leader Co-Dominant Leaders Limb Damage - Minor				
39 40	Areca Palm Live Oak	Dypsis lutescens Quercus virginiana	26	28 48	30 44	Good Fair	Apical Dieback Bent Leader Lopsided				
41	Pongam	Millettia pinnata	16	40	44	Good	Bent Leader Co-Dominant Leaders				
42	Live Oak Royal Palm	Quercus virginiana Roystonea regia	17 16	46 36	44 18	Fair Good	Co-Dominant Leaders Limb Damage - Minor				
44	Cabbage Palm	Sabal palmetto	12	6	14	Good					
45 46	Solitaire Palm Weeping Fig	Ptychosperma elegans Ficus benjamina	6 6	24 16	8 12	Good Good					
47	Slash Pine	Pinus elliottii	16	48	34	Good					
48 49	Weeping Fig Live Oak	Ficus benjamina Quercus virginiana	24 25	46 40	40 60	Fair Good	Co-Dominant Leaders Limb Damage - Minor On CLF				
50	Black Olive	Bucida buceras	10	28	22	Fair	Bent Leader Leaning - Minor				
51	Slash Pine	Pinus elliottii	5	24	14	Fair	Bent Leader Limb Damage - Minor				
52 53	Queen Palm Cabbage Palm	Syagrus romanzoffiana Sabal palmetto	9	16 14	14 12	Fair Good	Leaning				
54	Avocado	Persea americana	8	30	24	Good	Co-Dominant Leaders Co-Dominant Leaders Minor Book Structure				
55 56	Strangler Fig Black Olive	Ficus aurea Bucida buceras	31	26 60	24 54	Poor Good	Co-Dominant Leaders Limb Damage - Minor Poor Structure Partially Uprooted Slight Lean				
57	Montgomery Palm		8	16	12	Good					
58 59	Christmas Palm Black Olive	Adonidia merrillii Bucida buceras	5 30	8 48	6 50	Good Good					
60	Cabbage Palm	Sabal palmetto	10	28	14	Good	Co Deminant I and and Limb Demand. Minor				
61 62	Weeping Fig Cabbage Palm	Ficus benjamina Sabal palmetto	26 11	44 30	42 12	Fair Good	Co-Dominant Leaders Limb Damage - Minor				
63	Solitaire Palm	Ptychosperma elegans	2	22	6	Good					
64 65	Weeping Fig Laurel Oak	Ficus benjamina Quercus laurifolia	8 10	18 32	14 28	Good Fair	Limb Damage - Minor Poor Structure				
66	Black Olive	Bucida buceras	20	40	44	Fair	Co-Dominant Leaders Limb Damage - Minor Invasive vines				
67 68	Slash Pine Black Olive	Pinus elliottii Bucida buceras	26 21	46 40	40 40	Good Fair	Co-Dominant Leaders Limb Damage - Minor				
69	Black Olive	Bucida buceras	6	20	24	Poor	Co-Dominant Leaders Limb Damage - Minor Growing on rock edge o				
70 71	Cabbage Palm Cabbage Palm	Sabal palmetto Sabal palmetto	10 13	16 24	14 14	Good Good					
72	Cabbage Palm	Sabal palmetto	15	18	14	Good					
73 74	Strangler Fig Cabbage Palm	Ficus aurea Sabal palmetto	3 14	8 20	8 14	Fair Good	On dead stump				
75	Slash Pine	Pinus elliottii	18	44	30	Good					
76 77	Weeping Fig Slash Pine	Ficus benjamina Pinus elliottii	8 21	26 52	20 30	Fair Good	Bent Leader Co-Dominant Leaders Limb Damage - Minor Limb Damage - Minor				
78	Bird of paradise	Strelitzia reginae				Good					
79 80	Live Oak Washingtonia Palm	Quercus virginiana Washingtonia robusta	12 12	38 16	30 4	Fair Poor	Limb Damage - Minor Most Fronds Missing				
81	Black Olive	Bucida buceras	20	42	40	Fair	Limb Damage - Minor				
82 83	Live Oak	Quercus virginiana	26 30	48 44	60 50	Good Fair	Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor On CLF				
83 84	Weeping Fig Strangler Fig	Ficus benjamina Ficus aurea	30 5	14	12	Fair Fair	CO DOMINIANT FEAREIS FININ DAMAGE - MINOLION CFL				
85 86	Weeping Fig	Ficus benjamina	15	38 32	48 16	Good	Bent Leader Limb Damage - Minor				
86 87	Pink tabebuia Slash Pine	Tabebuia rosea Pinus elliottii	6 13	32 34	16 22	Fair Good	Lopsided				
88	Cabbage Palm	Sabal palmetto	12	12	16	Good	Co Dominant Londonal Linely Democratic Advis				
89 90	Weeping Fig Christmas Palm	Ficus benjamina Adonidia merrillii	6 4	20 8	16 6	Fair Good	Co-Dominant Leaders Limb Damage - Minor				
91	Florida Trema	Dia . W ···	6	24	18	Good	Bent Leader Limb Damage - Minor				
92 93	Slash Pine Slash Pine	Pinus elliottii Pinus elliottii	20	50	40	Good Dead	Limb Damage - Minor				
94	Bottle Palm	Hyophorbe lagenicaulis	8	10	6	Fair	Tapered and yellow fronds				
95 96	Live Oak Pink tabebuia	Quercus virginiana Tabebuia rosea	12 10	34 26	26 20	Fair Fair	Limb Damage - Minor Lopsided Trunk Damage - Minor Apical Dieback Bent Leader Mostly Defoliated				
97	Montgomery Palm	Veitchia arecina	6	18	6	Good	,				
98 99	Cabbage Palm Bottle Palm	Sabal palmetto Hyophorbe lagenicaulis	14 8	20 10	14 6	Good Good	Tapered				
100	Laurel Oak	Quercus laurifolia	63	30	22	Fair	Limb Damage - Minor				
101 102	Triangle Palm Slash Pine	Dypsis decaryi Pinus elliottii	12 18	16 44	18 26	Good Fair	Limb Damage - Minor Lopsided				
103	Black Olive	Bucida buceras	10	77	20	Dead	Line Damage Minor Leopsided				
104	Cabbage Palm	Sabal palmetto	14	14 44	12 50	Good Good					
105	Live Oak	Quercus virginiana	20	44	JU	<u> </u>					

TREE INVENTORY CHART										
ID#	Common Name	Botanical Name	DBH (inches)	Height (feet)	Spread (feet)	Condition	Notes			
106	Queen Palm	Syagrus romanzoffiana	10	24	14	Fair	Tapered Trunk			
107	Live Oak	Quercus virginiana	16	32	30	Fair	Bent Leader Limb Damage - Minor Lopsided			
108 109	Avocado Cabbage Palm	Persea americana Sabal palmetto	8 11	26 14	24 14	Good Good				
110	Cabbage Palm	Sabal palmetto	10	18	12	Good				
111	Queen Palm	Syagrus romanzoffiana	11	28	16		Bent Trunk Tapered Trunk			
112 113	Slash Pine Montgomery Palm	Pinus elliottii Veitchia arecina	15 5	48 14	24 6	Good Good				
114	Montgomery Palm		6	16	12	Good				
115	Cabbage Palm	Sabal palmetto	12	24	16	Good				
116	Live Oak	Quercus virginiana	12	32	30	Fair	Bent Leader Limb Damage - Minor Lopsided			
117 118	Solitaire Palm Cabbage Palm	Ptychosperma elegans Sabal palmetto	2 12	20 6	6 14	Good Fair	Growing on rock edge			
119	Laurel Oak	Quercus laurifolia	20	44	42	Good	Growing on rock eage			
120	Montgomery Palm		5	12	8	Good				
121	Royal Palm	Roystonea regia	19	36	16	Fair	Yellow Fronds			
122	Areca Palm	Dypsis lutescens		16	20	Good				
123 124	Crepe Myrtle Cabbage Palm	Lagerostroemia indica Sabal palmetto	14 11	30 20	20 14	Fair Good	Limb Damage - Minor			
125	Triangle Palm	Dypsis decaryi	12	18	18	Good				
126	Christmas Palm	Adonidia merrillii	4	8	6	Good				
127	Slash Pine	Pinus elliottii	16	44	26	Fair	Bent Leader Lopsided			
128	Laurel Oak	Quercus laurifolia	12	32	30	Fair	Roots growing on rock edge			
129 130	Birds of paradise Queen Palm	Strelitzia reginae Syagrus romanzoffiana	12	28 24	20 20	Good Good				
131	Cabbage Palm	Sabal palmetto	11	18	14	Good				
132	Cabbage Palm	Sabal palmetto	17	18	14	Good				
133	Weeping Fig	Ficus benjamina	8	24	16	Fair				
134	Queen Palm	Syagrus romanzoffiana	9	26	14	Good				
135 136	Cabbage Palm Cabbage Palm	Sabal palmetto Sabal palmetto	12 8	20 24	14 10	Good Good				
137	Black Olive	Bucida buceras	22	36	54	Good	Limb Damage - Minor			
138	Cabbage Palm	Sabal palmetto	11	16	14	Good				
139	Live Oak	Quercus virginiana	22	46	40	Good				
140	Cabbage Palm	Sabal palmetto	12 15	20	14 16	Good				
141 142	Royal Palm Cabbage Palm	Roystonea regia Sabal palmetto	15 12	28 16	16 14	Good Fair	Invasive vines			
143	Cabbage Palm	Sabal palmetto	12	4	12	Good				
144	Live Oak	Quercus virginiana	8	32	20	Fair	Bent Leader Limb Damage - Minor Lopsided			
145	Slash Pine	Pinus elliottii	9	38	22	Good				
146	Slash Pine	Pinus elliottii	19	42	26	Good	Assistable Dishark Co. Dominant London History Dominant Assista			
147 148	Live Oak Live Oak	Quercus virginiana Quercus virginiana	12 13	30 38	26 30	Fair Fair	Apical Dieback Co-Dominant Leaders Limb Damage - Minor Bent Leader Limb Damage - Minor			
149	Cabbage Palm	Sabal palmetto	12	22	12	Good	Leaning			
150	Banyan	Ficus benghalensis	71	40	80	Good	Co-Dominant Leaders Limb Damage - Minor			
151	Slash Pine	Pinus elliottii	16	42	28	Good				
152	Black Olive	Bucida buceras	18	30 6	18	Poor	Apical Dieback Limb Damage - Major Trunk Damage - Major			
153 154	Cabbage Palm Black Olive	Sabal palmetto Bucida buceras	12 13	32	14 22	Good Poor	 Co-Dominant Leaders Limb Damage - Major Trunk Damage - Major			
155	Royal Palm	Roystonea regia	16	34	18	Good	eo bommant teaders timb barrage ivajor mant barrage ivajor			
156	Live Oak	Quercus virginiana	15	34	30	Fair	Bent Leader Lopsided			
157	Live Oak	Quercus virginiana	24	40	48	Fair	Bent Leader Co-Dominant Leaders Included Bark Lopsided			
158	Slash Pine	Pinus elliottii	20	22	10	Dead	Doubt Trumbil Wallacus Francisch			
159 160	Royal Palm Cabbage Palm	Roystonea regia Sabal palmetto	20 16	32 6	18 16	Fair Good	Bent Trunk Yellow Fronds			
161	Black Olive	Bucida buceras	28	52	60	Good	Co-Dominant Leaders			
162	Christmas Palm	Adonidia merrillii	4	6	6	Good				
163	Slash Pine	Pinus elliottii	19	48	30	Good				
164 165	Live Oak Mango	Quercus virginiana Mangifera indica	16 12	38 34	36 30	Fair Good	Co-Dominant Leaders Limb Damage - Minor Lopsided			
166	Weeping Fig	Ficus benjamina	5	18	12	Good				
167	Cabbage Palm	Sabal palmetto	11	12	14	Good				
168	Bottle plam	Hyophorbe lagenicaulis	10	10	6	Good	Tapered trunk			
169	Cabbage Palm	Sabal palmetto	12	10	14	Good	A : 10: 1 11: 10 Ar			
170 171	Black Olive Cabbage Palm	Bucida buceras Sabal palmetto	18 10	36 8	40 14	Fair Good	Apical Dieback Limb Damage - Minor			
172	Areca Palm	Dypsis lutescens	10	20	20	Good				
173	Royal Palm	Roystonea regia	18	36	14	Fair	Yellow Fronds			
174	Slash Pine	Pinus elliottii	16	48	34	Good				
175	Montgomery Palm		4	14	6	Good	Co Dominant Landamilla de 1880 de 1881 de 200			
176 177	Bottlebrush Cabbage Palm	Callistemon citrinus Sabal palmetto	10 142	26 6	24 14	Fair Good	Co-Dominant Leaders Leaning - Minor Limb Damage - Minor			
178	Slash Pine	Pinus elliottii	144	U	14	Dead				
179	Cabbage Palm	Sabal palmetto	14	20	16	Good				
180	Slash Pine	Pinus elliottii	16	46	30	Good				
181	Yucca Weening Fig	Yucca Ficus heniamina	14 6	24 20	28 12	Good				
182 183	Weeping Fig Cabbage Palm	Ficus benjamina Sabal palmetto	11	20	12 14	Fair Good				
184	Cabbage Palm	Sabal palmetto	12	16	14	Good				
185	Live Oak	Quercus virginiana	12	26	24	Fair	Co-Dominant Leaders Included Bark			
186	Black Olive	Bucida buceras	13	34	30	Fair	Apical Dieback Bent Leader Limb Damage - Minor			
187 188	Cabbage Palm Live Oak	Sabal palmetto Quercus virginiana	14 28	12 46	14 70	Good Good	Co-Dominant Leaders Limb Damage - Minor			
188	Mango	Quercus virginiana Mangifera indica	12	34	30	Good Good	CO DOMINIANT FEAREIS FILID DAMAGE - MILIOI			
190	Pink tabebuia	Tabebuia rosea	6	26	20	Fair	Bent Leader Limb Damage - Minor Lopsided			
191	Black Olive	Bucida buceras	18	38	36	Good	Co-Dominant Leaders Limb Damage - Minor			
192	Cabbage Palm	Sabal palmetto	11	18	12	Good				
193 194	Black Olive Christmas Palm	Bucida buceras Adonidia merrillii	18 4	46 8	34 6	Good Good				
194 195	Cabbage Palm	Sabal palmetto	10	8 14	16	Good Good				
196	Black Olive	Bucida buceras	10	32	26	Fair	Bent Leader Limb Damage - Minor Lopsided			
197	Royal Palm	Roystonea regia	17	36	16	Poor	Yellow Fronds Woodpecker damage			
198	Cabbage Palm	Sabal palmetto	11	10	12	Good				
199 200	Weeping Fig	Ficus benjamina Sabal palmetto	24 14	44 20	40 14	Fair Good	Co-Dominant Leaders Limb Damage - Minor On CLF			
200	Cabbage Palm Paradise Tree	Sabal palmetto Simarouba glauca	14 8	20 26	14 24	Good Good				
201	Slash Pine	Pinus elliottii	20	46	40	Good				
203	Cabbage Palm	Sabal palmetto	12	4	12	Fair				
204	Slash Pine	Pinus elliottii	15	40	36	Good				
	Slash Pine	Pinus elliottii	17	48	34	Good				
205	Cabbage Palm	Sabal palmetto Dypsis lutescens	12	30	24	Dead Good				
205 206	Areca Palm	レッヤンい はしこしこしこ	ļ							
205	Areca Palm Slash Pine	Pinus elliottii	24	50	30	Good				
205 206 207 208 209	Slash Pine Cabbage Palm	Pinus elliottii Sabal palmetto	10	10	12	Good				
205 206 207 208	Slash Pine	Pinus elliottii					Bent Leader Co-Dominant Leaders Limb Damage - Minor			



CONSULTANTS:

ARCHITECT:
Justin Architects
2400 E. Commercial Boulevard, Suite 201
Fort Lauderdale, FL 33308
(954) 771-2724
www.justinarc.com

MEP: SGM Engineering 5805 Blue Lagoon Drive, Suite 285 Miami, Florida 33026 (954) 421-1944 www.sgmengineering.com

STRUCTURAL ENGINEER:
Master Consulting Engineers
4101 Ravenswood Road, Suite 320
Fort Lauderdale, Florida 33312
(954) 210-7671
www.mcengineers.com

SUSTAINABILITY CONSULTANT: SOCOTEC Consulting, Inc. 1177 Clare Avenue, Suite 7 West Palm Beach, Florida 33401 (561) 801-7576 www.spinnakergroup.com

GEOTECHNICAL:
Pacifica Engineering Services
601 N. Congress Avenue, Suite 303
Delray Beach, Florida 33445
(561) 419-8460
www.pacificaes.com

CLIENT:



4900 W. Copans Road Coconut Creek, FL 33063


PROJECT NAME:

OAK TRAILS PARK IMPROVEMENTS

4230 NW. 74th Street Coconut Creek, FL 33073

SEAL:

I HEREBY CERTIFY THAT THE INFORMATION HEREON MEETS STANDARDS OF PRACTICE AS SET FORTH BY THE FLORIDA DEPARTMENT OF AGRICULTURE AND CONSUMER SERVICES OF PROFESSIONAL SURVEYORS AND MAPPERS IN CHAPTER 5J-17, FLORIDA ADMINISTRATIVE CODE, PURSUANT TO SECTION 472.027, FLORIDA STATUTES.



NOT VALID WITHOUT THE SIGNATURE AND
THE ORIGINAL RAISED SEAL OF A FLORIDA
LICENSED SURVEYOR AND MAPPER.

APPROVED: MARTIN P. ROSSI, PSM

FLA. REGISTRATION NO. 5857

DATE 02/12/24

1 09/12/24 DRC SITE PLAN RESUBMITTAL

ı		00/12/21	5		,			_	
ı	1	07/29/24	REV.	TO	SHOW	ELEC.	SERV.	BOX	SYMBO
ı									
ı									
ı									
ı									
ı	NO.	DATE			F	REVI	SIOI	N S	
L					· ·				The second second

SUBMITTAL:

DRC SUBMITTAL

DATE ISSUED:
PROJECT NUMBER:
DRAWN BY:
REVIEWED BY:
DESIGNED BY:

09/16/2024 23-00155

SHEET TITLE:

SKETCH OF BOUNDARY &

TOPOGRAPHIC SURVEY

SHEET NUMBER:

213 214 215 216 217 218 219 220	Christmas Palm	Adonidia merrillii	3	26 6	24 5	Fair Good	Co-Dominant Leaders Leaning - Minor
216 217 218 219	Washingtonia Palm	Washingtonia robusta	12	6	8	Good	
218 219	Christmas Palm Paradise Tree	Adonidia merrillii Simarouba glauca	<u>4</u> 8	6 24	6 20	Good Good	
219	Cabbage Palm	Sabal palmetto	9	10	14	Good	
220	Australian Pine Laurel Oak	Casuarina equisetfolia Quercus laurifolia	24 6	46 26	26 20	Good Good	
	Slash Pine	Pinus elliottii	18	38	28	Good	Limb Damage - Minor
221	Live Oak Slash Pine	Quercus virginiana Pinus elliottii	11 20	38 42	30 26	Good Fair	Apical Dieback Limb Damage - Minor Lopsided
223	Slash Pine	Pinus elliottii	17	46	30	Good	
224 225	Cabbage Palm Slash Pine	Sabal palmetto Pinus elliottii	12 13	16 40	14 30	Good Good	
226	Slash Pine	Pinus elliottii	19	46	24	Good	
227 228	Cabbage Palm Slash Pine	Sabal palmetto Pinus elliottii	12	26	16	Good Dead	
229	Cabbage Palm	Sabal palmetto	8	12	14	Good	
230 231	Slash Pine Christmas Palm	Pinus elliottii Adonidia merrillii	14 8	42 16	30 10	Good Good	Lopsided
232	Strangler Fig	Ficus aurea	14	30	30	Fair	Growing on a rock
233 234	Cabbage Palm Cabbage Palm	Sabal palmetto Sabal palmetto	11 10	14 14	14 14	Good Good	
235	Cabbage Palm	Sabal palmetto	11	16	14	Good	
236 237	Black Olive Live Oak	Bucida buceras Quercus virginiana	23 14	38 36	40 30	Fair Fair	Apical Dieback Co-Dominant Leaders Limb Damage - Major Leaning - Major Limb Damage - Minor Lopsided Trunk Damage -
238	Live Oak	Quercus virginiana	5	18	18	Good	Leaning - Major Limb Damage - Minor Lopsided Trunk Damage -
239 240	Cabbage Palm	Sabal palmetto	12	8 40	16 40	Good	
241	Black Olive Slash Pine	Bucida buceras Pinus elliottii	18 22	54	40	Good Good	Limb Damage - Minor
242	Slash Pine	Pinus elliottii	15	44	22	Fair	Apical Dieback Limb Damage - Minor Invasive vines
243 244	Slash Pine Cabbage Palm	Pinus elliottii Sabal palmetto	14 10	42 18	32 14	Good Good	
245	Cabbage Palm	Sabal palmetto	12	8	14	Good	
246 247	Weeping Fig Live Oak	Ficus benjamina Quercus virginiana	<u>4</u> 20	18 46	14 44	Fair Fair	Bent Leader
248	Laurel Oak	Quercus laurifolia	26	48	50	Fair	Co-Dominant Leaders
249 250	Slash Pine Japanese Fern tree	Pinus elliottii Filicium decipiens	15 14	44 36	26 44	Fair Fair	Apical Dieback Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor
251	Java Bishopwood	Bischofia javanica	32	60	60	Poor	Co-Dominant Leaders Limb Damage - Major
252 253	Live Oak Slash Pine	Quercus virginiana Pinus elliottii	16 6	34 30	36 12	Fair Fair	Apical Dieback Co-Dominant Leaders Lopsided Limb Damage - Minor Lopsided Mostly Defoliated
254	Solitaire Palm	Ptychosperma elegans	3	20	6	Good	Limb Damage - Willion Lobsided Wostry Defonated
255 256	Cabbage Palm Live Oak	Sabal palmetto Quercus virginiana	14 8	18 26	14 24	Good Fair	Co-Dominant Leaders Leaning - Minor Limb Damage - Minor
257		Ptychosperma macarthuri	4	12	8	Good	Co-Dominant Leaders Leaning - Wilhor Limb Damage - Wilhor
258	Christmas Palm	Adonidia merrillii	5	8	6	Good	
259 260	Yucca Areca Palm	Yucca Dypsis lutescens	8	12 10	20 20	Good Good	
261	Weeping Fig	Ficus benjamina	6	18	16	Fair	Bent Leader Co-Dominant Leaders Limb Damage - Minor
262 263	Cabbage Palm Cabbage Palm	Sabal palmetto Sabal palmetto	12 12	16 14	14 14	Good Good	
264	Strangler Fig	Ficus aurea	36	42	60	Good	Limb Damage - Minor
265 266	Cabbage Palm Weeping Fig	Sabal palmetto Ficus benjamina	14 4	24 16	14 8	Fair Fair	Invasive vines
267	Black Olive	Bucida buceras	22	46	50	Good	Co-Dominant Leaders Leaning - Minor
268 269	Slash Pine Washingtonia Palm	Pinus elliottii Washingtonia robusta	20 14	54 16	34 14	Good Good	
270	Slash Pine	Pinus elliottii	11	42	24	Good	
271 272	Slash Pine Solitaire Palm	Pinus elliottii Ptychosperma elegans	19 2	46 18	38 6	Good Good	Limb Damage - Minor
273	Cabbage Palm	Sabal palmetto	11	8	14	Good	
274 275	Umbrella Tree Royal Palm	Schefflera actinophylla Roystonea regia	12 16	26 34	20 14	Fair Fair	Co-Dominant Leaders Yellow Fronds
276	Slash Pine	Pinus elliottii	14	44	28	Good	Yellow Florids
277	Cabbage Palm	Sabal palmetto	11	16	14	Good	
278 279	Cabbage Palm Areca Palm	Sabal palmetto Dypsis lutescens	15	14 16	16 20	Good Good	
280	Cabbage Palm	Sabal palmetto	13	14	14	Good	
281 282	Laurel Oak Slash Pine	Quercus laurifolia Pinus elliottii	6 18	26 48	24 28	Good Good	Limb Damage - Minor Lopsided
283	Cabbage Palm	Sabal palmetto	12	26	12	Good	
284 285	Australian Pine Australian Pine	Casuarina equisetfolia Casuarina equisetfolia	5 3	22 20	20 10	Good Good	
286	Australian Pine	Casuarina equisetfolia	3	18	14	Good	
	Slash Pine Laurel Oak	Pinus elliottii Quercus laurifolia	20 7	48 28	30 24	Good Fair	Bent Leader Limb Damage - Minor Lopsided
287 288	Slash Pine	Pinus elliottii	16	40	22	Good	Bent Leader
288 289	Ficus Spp.		26	44	60	Good	Co-Dominant Leaders Limb Damage - Minor
288 289 290	Live Oak	Quercus virainiana	11	32	3በ	Good	
288 289 290 291 292	Live Oak Live Oak	Quercus virginiana Quercus virginiana	11 10	32 32	30 30	Good Good	
288 289 290 291 292 293	Live Oak Live Oak	Quercus virginiana Quercus virginiana	10 10	32 34	30 30	Good Good	Limb Damage - Minor
288 289 290 291 292	Live Oak	Quercus virginiana	10	32	30	Good	Limb Damage - Minor
288 289 290 291 292 293 294 295 296	Live Oak Live Oak Live Oak Live Oak Live Oak	Quercus virginiana Quercus virginiana Quercus virginiana Quercus virginiana Quercus virginiana	10 10 10 10 10	32 34 28 28 34	30 30 30 30 30 30	Good Good Good Good	Limb Damage - Minor Co-Dominant Leaders Sprouting
288 289 290 291 292 293 294 295	Live Oak Live Oak Live Oak Live Oak	Quercus virginiana Quercus virginiana Quercus virginiana Quercus virginiana	10 10 10 10	32 34 28 28	30 30 30 30	Good Good Good	
288 289 290 291 292 293 294 295 296 297 298	Live Oak Slash Pine	Quercus virginiana Pinus elliottii	10 10 10 10 11 11 9	32 34 28 28 34 32 30 42	30 30 30 30 30 30 26 22 24	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders
288 289 290 291 292 293 294 295 296 297	Live Oak Slash Pine Slash Pine	Quercus virginiana	10 10 10 10 11 11 9	32 34 28 28 34 32 30	30 30 30 30 30 30 26 22	Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia	10 10 10 10 11 11 9 15 15 10	32 34 28 28 34 32 30 42 42 42 16 36	30 30 30 30 30 26 22 24 24 24 12 40	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak Live Oak	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia Quercus virginiana	10 10 10 10 11 11 9 15 15 10 16 8	32 34 28 28 34 32 30 42 42 42 16 36 26	30 30 30 30 30 26 22 24 24 12 40 20	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia	10 10 10 10 11 11 9 15 15 10	32 34 28 28 34 32 30 42 42 42 16 36	30 30 30 30 30 26 22 24 24 24 12 40	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak Live Oak Royal Poinciana Areca Palm	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia Quercus virginiana Quercus virginiana Quercus virginiana Delonix regia Dypsis lutescens	10 10 10 10 11 11 11 9 15 15 10 16 8	32 34 28 28 34 32 30 42 42 42 16 36 26 28 30 14	30 30 30 30 30 26 22 24 24 12 40 20 22 36 12	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Bent Leader
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak Live Oak Live Oak Royal Poinciana	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia Quercus virginiana Quercus virginiana Quercus virginiana Quercus virginiana	10 10 10 10 11 11 11 9 15 15 10 16 8	32 34 28 28 34 32 30 42 42 16 36 26 28 30	30 30 30 30 30 26 22 24 24 12 40 20 22 36	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Bent Leader
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak Live Oak Live Oak Areca Palm Areca Palm Areca Palm	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia Quercus virginiana Quercus virginiana Quercus virginiana Delonix regia Dypsis lutescens Dypsis lutescens Dypsis lutescens	10 10 10 10 11 11 11 9 15 15 10 16 8	32 34 28 28 34 32 30 42 42 42 16 36 26 28 30 14 15 14	30 30 30 30 30 30 26 22 24 24 12 40 20 22 36 12 12 12	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Bent Leader
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak Live Oak Royal Poinciana Areca Palm Areca Palm	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia Quercus virginiana Quercus virginiana Quercus virginiana Delonix regia Dypsis lutescens Dypsis lutescens	10 10 10 10 11 11 11 9 15 15 10 16 8	32 34 28 28 34 32 30 42 42 42 16 36 26 28 30 14 15 14	30 30 30 30 30 30 26 22 24 24 12 40 20 22 36 12 12 12	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Bent Leader
288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310	Live Oak Slash Pine Slash Pine Cabbage Palm Laurel Oak Live Oak Live Oak Areca Palm Areca Palm Areca Palm Areca Palm	Quercus virginiana Pinus elliottii Pinus elliottii Sabal palmetto Quercus laurifolia Quercus virginiana Quercus virginiana Quercus virginiana Delonix regia Dypsis lutescens Dypsis lutescens Dypsis lutescens Dypsis lutescens Dypsis lutescens	10 10 10 10 11 11 11 9 15 15 10 16 8	32 34 28 28 34 32 30 42 42 42 16 36 26 28 30 14 15 14 14 13	30 30 30 30 30 26 22 24 24 12 40 20 22 36 12 12 12 12 12	Good Good Good Good Good Good Good Good	Co-Dominant Leaders Sprouting Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Co-Dominant Leaders Limb Damage - Minor Bent Leader

12 Good

314 Areca Palm *Dypsis lutescens*

315	Areca Palm	Dypsis lutescens		14	12	Good	
316	Areca Palm	Dypsis lutescens		14	12	Good	
317	Areca Palm	Dypsis lutescens		15	12	Good	
318	Areca Palm	Dypsis lutescens		15	12	Good	
319	Areca Palm	Dypsis lutescens		15	12	Good	
320	Areca Palm	Dypsis lutescens		15	12	Good	
321	Areca Palm	Dypsis lutescens		15	12	Good	
322	Areca Palm	Dypsis lutescens		15	12	Good	
323	Areca Palm	Dypsis lutescens		15	12	Good	
324	Areca Palm	Dypsis lutescens		15	12	Good	
325	Areca Palm	Dypsis lutescens		15	12	Good	
326	Areca Palm	Dypsis lutescens		15	12	Good	
327	Areca Palm	Dypsis lutescens		15	12	Good	
328	Areca Palm	Dypsis lutescens		15	12	Good	
329	Slash Pine	Pinus elliottii	22	44	34	Good	Limb Damage - Minor
330	Spanish Dagger	Yucca gloriosa	10	16	20	Good	Cluster



www.millerlegg.com

CONSULTANTS:

ARCHITECT: Justin Architects 2400 E. Commercial Boulevard, Suite 201 Fort Lauderdale, FL 33308 (954) 771-2724 www.justinarc.com

SGM Engineering 5805 Blue Lagoon Drive, Suite 285 Miami, Florida 33026 (954) 421-1944 www.sgmengineering.com

STRUCTURAL ENGINEER: Master Consulting Engineers 4101 Ravenswood Road, Suite 320 Fort Lauderdale, Florida 33312 (954) 210-7671 www.mcengineers.com

SUSTAINABILITY CONSULTANT: SOCOTEC Consulting, Inc. 1177 Clare Avenue, Suite 7 West Palm Beach, Florida 33401 (561) 801-7576 www.spinnakergroup.com

GEOTECHNICAL: Pacifica Engineering Services
601 N. Congress Avenue, Suite 303
Delray Beach, Florida 33445
(561) 419-8460
www.pacificaes.com




4900 W. Copans Road Coconut Creek, FL 33063

PROJECT NAME:

OAK TRAILS PARK **IMPROVEMENTS**

4230 NW. 74th Street Coconut Creek, FL 33073

I HEREBY CERTIFY THAT THE INFORMATION HEREON MEETS STANDARDS OF PRACTICE AS SET FORTH BY THE FLORIDA DEPARTMENT OF AGRICULTURE AND CONSUMER SERVICES OF PROFESSIONAL SURVEYORS AND MAPPERS IN CHAPTER 5J-17, FLORIDA ADMINISTRATIVE CODE, PURSUANT TO SECTION 472.027, FLORIDA STATUTES.



NOT VALID WITHOUT THE SIGNATURE AND THE ORIGINAL RAISED SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER.

APPROVED: MARTIN P. ROSSI, PSM

FIA REGISTRATION NO 5857

MATERIAL PROPERTY OF THE PR

1 09/12/24 DRC SITE PLAN RESUBMITTAL

	1	07/29/24	REV.	ТО	SHOW	ELEC.	SERV.	BOX	SYMB
	NO.	DATE			F	REVI	SIOI	N S	
_									

SUBMITTAL:

DRC SUBMITTAL


DATE ISSUED: PROJECT NUMBER: **DRAWN BY: REVIEWED BY:**

SHEET TITLE:

DESIGNED BY:

SKETCH OF BOUNDARY & TOPOGRAPHIC SURVEY

SHEET NUMBER:





CONSULTANTS:

ARCHITECT: **Justin Architects** 2400 E. Commercial Boulevard, Suite 201 Fort Lauderdale, FL 33308

SGM Engineering 5805 Blue Lagoon Drive, Suite 285 Miami, Florida 33026

STRUCTURAL ENGINEER: Master Consulting Engineers 4101 Ravenswood Road, Suite 320

(954) 210-7671 www.mcengineers.com SUSTAINABILITY CONSULTANT: SOCOTEC Consulting, Inc. 1177 Clare Avenue, Suite 7

West Palm Beach, Florida 33401 (561) 801-7576 www.spinnakergroup.com **GEOTECHNICAL:**

Pacifica Engineering Services 601 N. Congress Avenue, Suite 303 Delray Beach, Florida 33445 (561) 419-8460 www.pacificaes.com




Coconut Creek, FL 33063

PROJECT NAME:

OAK TRAILS PARK **IMPROVEMENTS**

4230 NW. 74th Street Coconut Creek, FL 33073

I HEREBY CERTIFY THAT THE INFORMATION HEREON MEETS STANDARDS OF PRACTICE AS SET FORTH BY THE FLORIDA DEPARTMENT OF AGRICULTURE AND CONSUMER SERVICES OF ROFESSIONAL SURVEYORS AND MAPPERS IN CHAPT 5J-17, FLORIDA ADMINISTRATIVE CODE, PURSUANT



NOT VALID WITHOUT" THE ORIGINAL RAISED SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER.

APPROVED: MARTIN P. ROSSI, PSM

1 09/12/24 DRC SITE PLAN RESUBMITTAL REVISIONS

SUBMITTAL:

DRC SUBMITTAL

DATE ISSUED: PROJECT NUMBER: **DRAWN BY: REVIEWED BY:**

09/16/2024

23-00155

SKETCH OF TOPOGRAPHIC **SURVEY**

SHEET NUMBER: