

Overgrown and bare areas along NW 22nd Roard.



Invasive plant material along NW 22nd Road.



Bare areas and grading issues along NW 22nd Road.



Grading and invasive plants along south side of NW 22nd Street.



Overgrown Ficus hedge and invasive plants along south side of NW 22nd Street.



Invasive plants along berm on south side of NW 22nd Street.

